



STAMPS AUTO - SAN TAN

40815 N Ironwood Suite A106
 San Tan Valley, AZ 85142
 480-987-5873

Please leave us a review if you are pleased with our service
 "Dealership Quality At Neighborhood Prices"
 Visit us online at www.Stampsauto.com

8/19/2019 4:49:29 PM

Repair Order #28953 - Sub Est 10

Page:1

AZ CARE

Phone: 801-865-2211

543 E. Shawnee Rd.
 San Tan Valley AZ, 85140

Service Writer : KBST

Vehicle : 1994 Ford E150 1/2 Ton Econoline Club Wagon 5.8 L 351 CID V8 Windsor

VIN : 1FMEE11H6RHB63506

Tag/State : BST6640/AZ

Fleet #/Driver

Created : 8/15/2019 1:10:59 PM

Odometer In : 92989

Odometer Out : 92989

Labor/Notes

Technician	Description	Price
ABST	TRANSMISSION OIL FILTER Remove & Replace	\$156.60
ABST	Clean and Adjust Rear Drum Brakes	\$49.85
ABST	Clean and Lubricate Front Disc Brakes	\$124.63
ABST	DIFFERENTIAL SERVICE	\$74.78
ABST	ALTERNATOR DRIVE BELT Remove & Replace	\$133.43
ABST	Includes: Serpentine and V-Belt type Belt(s). SHOCK &/OR STRUT ASSEMBLY Remove & Install or Remove & Replace	\$123.47
ABST	DOES NOT include disassemble or alignment. SHOCK &/OR STRUT ASSEMBLY Remove & Install or Remove & Replace	\$123.47
ABST	DOES NOT include disassemble or alignment. 2 WHEEL ALIGNMENT	\$69.99
	2 WHEEL COMPUTERIZED ALIGNMENT INCLUDES: CHECK TIRE PRESSURE, CHECK WHEEL RUN OUT, INSPECT STEERING LINKAGES & SUSPENSION COMPONENTS FOR WEAR OR DAMAGE. CHECK PRESENT ALIGNMENT CONDITION, ALIGN FRONT TO SPECIFICATION. (4X4 SHIMMING & CAMKITS EXTRA)	

Parts

Qty	Code	Description	Condition	Unit Price	Price
2		Wiper Blade 22 in		\$8.36	\$16.72
1		A/Trans Filter Kit (Rubber Coated Metal OE Style - Platinum)		\$92.35	\$92.35
7		Note: w/ E4OD Transmission;w/ Deep Pan;Refer to Tech Bulletin;w/ 20 Bolt Pan Automatic Transmission Fluid	New	\$5.25	\$36.75
1		Transmission Pan		\$64.44	\$64.44
4		80/90 LIMITED SLIP Gear Oil	New	\$17.95	\$71.80
1		Differential Carrier Gasket - Rear Axle		\$25.28	\$25.28
1		Note: w/ 10 Bolt Holes;w/ 8.8" Ring Gear Belt		\$80.60	\$80.60
1		Note: Under 8,500 lb. GVW Radiator Cap		\$18.00	\$18.00
2		Note: 13 lbs.;Standard Shock Absorber - OESpectrum - Front		\$112.65	\$225.30
2		Note: Recommended OE Application -Specific Replacement Shock Absorber - OESpectrum - Rear		\$112.65	\$225.30
		Note: Recommended OE Application -Specific Replacement			

Labor	\$856.22
Parts	\$856.54
Tires	\$0.00
Wheels	\$0.00
Sublet/Misc.	\$0.00



STAMPS AUTO - SAN TAN

40815 N Ironwood Suite A106
San Tan Valley, AZ 85142
480-987-5873

Please leave us a review if you are pleased with our service
"Dealership Quality At Neighborhood Prices"
Visit us online at www.Stampsauto.com

8/19/2019 4:49:29 PM

Repair Order #28953 - Sub Est 10

Page:2

AZ CARE

Vehicle: 1994 Ford E150 1/2 Ton Econoline Club

Job Supplies	\$85.00
Charges	\$0.00
Sales Tax	Default Rule @ 7.2%	\$67.79

Repair Total \$1,865.55

Technician Code Certification #
ABST

Approvals

Date & Time	Total Amount	Authorized By	Method	Employee
8/15/2019 1:12 PM	\$0.00	AZ CARE	In Person	KBST

Reason:

I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that you (Stamps Auto) are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for testing and/or inspection. An express garage keeper's lien is hereby acknowledged on above vehicle to secure the amount or repairs thereto. All vehicles left over 48 hrs. after repairs are completed WILL INCUR A \$5.00 PER DAY STORAGE FEE. 36 Month or 36,000 Mile Warranty on Parts & Labor Nationwide Peace of Mind Warranty at any Napa Autocare Location. Traveling customers can call 1-800-538 6272 to start a claim. At Stamps Auto, we strive for the perfection of our products, services, and the satisfaction of our customers. If you experienced these services today please take the time to give us a review on Google, and or Yelp.com.

If you have any additional comments or suggestions that would better assist our services to our customers, please contact John our Onwer at John@stampsauto.com

Customer Signature _____